

# DairyScale Platform Loadcell Upgrade Kit


### Upgrade Kit contains:

- 3 x Loadcell Kit
- 1 x DairyScale junction box
- 6 x DairyScale platform adaptor
- 6 x DairyScale foot adaptor
- 48 x M8X30 SS T304 cap screw
- 18 x M10x50 SS T304 cap screw
- 18 x M10 SS T304 spring washer

#### Tools required

• #6, #8 allen key/cordless drill and #6, #8 allen bit


# Installation



NOTE: use cable ties through existing holes under the steelwork to attach cable and junction box assembly.

### Connecting cables to the scale

## Weighing Platform connectors



### **IMPORTANT**

- Apply small quantity of Loctite 501 to threads of all loadcell bolts prior to assembly.
- Use torque brench to apply correct tension to bolts on final assembly.

M8 cap screws - 20Nm M10 cap screws - 40 Nm

